

---

# Tiptel33XX—Release Notes

## Introduction:

### ❖ Product Model:

Tiptel 3340/Tiptel 3330/Tiptel 3320/Tiptel 3310/

### ❖ Firmware Version:

2.0.4.6.31

### ❖ Release Date:

2020.11.13

**Version: 2.0.4.6.31**

## New Add Features

- N/A.

## Improve Features

- G722 makes noise immediately after answering.
- The BT function removes the behavior of blocking the MAC address of the B\_link manufacturer.

## Bug fixes

- Fixed the issue that phone does not revert to Primary SIP Server from Failover SIP Server when Primary SIP Server returns to normal.
- Fixed the issue that the first letter of the name is uppercase or contain uppercase letters, input uppercase letters, can not find all contacts in Prefix / Fuzzy search mode.
- Fixed the issue that account password containing % 2 and % b, which is inconsistent with the original password after the phone is assigned.
- Fixed the issue that BLF Pick up fails.
- Fixed the issue that headset mode is turned off after incoming call.

---

## Version: 2.0.4.6.30

### New Add Features

- N/A.

### Improve Features

- N/A.

### Bug fixes


- Blind Transfer by BLF.([SUPPORT-651](#))

Add configuration option to make the phone blind transfer by BLF:

Web->Setting->Features->Forward->Forward By Dsskey, P25049: 0-Off, 1-On, default is Off.

Off: Old Mode(New Call).

On: Press Dsskey in the incoming call state, the call will be forwarded.



**Scene1:** A call B, B no answer, B press Softkey "Forward" then B press BLF key C. The result is B return to the idle state, extension C rings.

**Scene2:** A call B, B no answer, B press BLF key C. The result is B return to the idle state, extension C rings.

## Version: 2.0.4.6.29

### New Add Features

- N/A.

### Improve Features

- N/A.

### Bug fixes

- Flashing first and last display key.([SUPPORT-608](#))
- Import contacts from FRITZ!Box.([SUPPORT-346](#))

